

Dir	Local Time	CAN ID	Data Hex	Data ASCII	Src	Dst	Data Type
RK	20:24:17.222436	87040A7C	02 8C 5E	..*	124		uavcan_equipment_esc_Status
RK	20:24:17.222436	1E3FF27C	05 A2 B5 3F 75 64 66 D6	.b..udf.	124		uavcan_protocol_debug_KeyValue
RK	20:24:17.222437	1E3FF27C	AE DE C6 40 75 71 66 D7	..duf.	124		uavcan_protocol_debug_KeyValue
RK	20:24:17.2227437	80840601	E8 66 00 02 65 99 96 97	.f.e...	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.2227437	80840601	66 59 99 64 77	fy.du	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.230438	1E3FF27A	09 5F E3 BC 69 64 66 DC	...idf.	122		uavcan_protocol_debug_KeyValue
RK	20:24:17.231438	1E3FF27A	1F 24 0C 3F 69 71 66 D0	..7idf.	122		uavcan_protocol_debug_KeyValue
RK	20:24:17.231438	87040A7A	84 C2 00 00 00 00 FE 8A	122		uavcan_equipment_esc_Status
RK	20:24:17.231438	87040A7A	4D 32 31 BB 5C EE 0E 2A	M21...*	122		uavcan_equipment_esc_Status
RK	20:24:17.231438	87040A7A	03 08 4A	..J	122		uavcan_equipment_esc_Status
RK	20:24:17.231438	1E3FF27A	56 06 BC 3F 75 64 66 DE	V..udf.	122		uavcan_protocol_debug_KeyValue
RK	20:24:17.231438	1E3FF27A	16 C7 40 75 71 66 D9	..duf.	122		uavcan_protocol_debug_KeyValue
RK	20:24:17.232439	80840601	E8 66 00 02 65 99 96 98	.f.e...	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.232439	80840601	66 59 99 64 78	fy.dx	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.238440	80840601	E8 66 00 02 65 99 96 99	.f.e...	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.238440	80840601	66 59 99 64 79	fy.dy	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.240440	1E3FF279	05 50 F7 09 69 64 66 CB	..P..idf.	121		uavcan_protocol_debug_KeyValue
RK	20:24:17.240440	1E3FF279	07 4C F0 3E 69 71 66 C1	..L..idf.	121		uavcan_protocol_debug_KeyValue
RK	20:24:17.241440	87040A79	DE 08 00 00 00 00 01 8E	121		uavcan_equipment_esc_Status
RK	20:24:17.241440	87040A79	4E 07 31 87 5C F0 0E 2E	N.1.1...	121		uavcan_equipment_esc_Status
RK	20:24:17.241440	87040A79	01 04 4E	..N	121		uavcan_equipment_esc_Status
RK	20:24:17.241440	1E3FF279	F8 C4 C6 3F 75 64 66 C3	...udf.	121		uavcan_protocol_debug_KeyValue
RK	20:24:17.241440	1E3FF279	DE C8 C6 40 75 71 66 C3	..duf.	121		uavcan_protocol_debug_KeyValue
RK	20:24:17.242440	80840601	E8 66 00 02 65 99 96 9A	.f.e...	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.242440	80840601	66 59 99 64 7A	fy.dz	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.247441	80840601	E8 66 00 02 65 99 96 9B	.f.e...	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.247441	80840601	66 59 99 64 7B	fy.d[1		uavcan_equipment_esc_RawCommand
RK	20:24:17.252442	80840601	E8 66 00 02 65 99 96 9C	.f.e...	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.252442	80840601	66 59 99 64 7C	fy.d]	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.256443	80840601	FF 95 00 00 04 00 10 9D	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.256443	80840601	00 40 01 00 7D	.@.}	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.262444	80840601	E8 66 00 02 65 99 96 9E	.f.e...	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.262444	80840601	66 59 99 64 7E	fy.d-	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.267445	80840601	E8 66 00 02 65 99 96 9F	.f.e...	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.267445	80840601	66 59 99 64 7F	fy.d.	1		uavcan_equipment_esc_RawCommand
RK	20:24:17.270446	1E3FF27D	7C F8 82 8D 69 64 66 C4	...idf.	125		uavcan_protocol_debug_KeyValue
RK	20:24:17.270446	1E3FF27D	07 60 4F 3F 69 71 66 C5	..0Hidf.	125		uavcan_protocol_debug_KeyValue
RK	20:24:17.271446	87040A7D	14 FF 00 00 00 00 FD 92	125		uavcan_equipment_esc_Status
RK	20:24:17.271446	87040A7D	4D B5 38 BC 5C C4 0E 32	M.8.\..2	125		uavcan_equipment_esc_Status
RK	20:24:17.271446	87040A7D	04 10 52	..R	125		uavcan_equipment_esc_Status

Dir	Local Time	CAN ID	Data Hex	Data ASCII	Src	Dst	Data Type
RX	20:24:17.271446	07040A7D	04 10 52	..R	125		uavcan.equipment.esc.Status
RX	20:24:17.271446	1E3FF27D	79 69 AC 3F 75 64 66 C6	yi.?udf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.271446	1E3FF27C	43 79 94 BD 69 64 66 D8	Cy..idf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.271446	1E3FF27D	81 AD C5 40 75 71 66 C7	...@uqf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.271446	1E3FF27C	B4 C9 6A 3F 69 71 66 D9	..j?iqf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.272446	07040A7C	4F 0E 00 00 00 FF 9F	O.....	124		uavcan.equipment.esc.Status
RX	20:24:17.272446	07040A7C	4D 5D 38 B7 5C C3 0E 3F	M]8.\..?	124		uavcan.equipment.esc.Status
RX	20:24:17.272446	07040A7C	04 0C 5F	.._	124		uavcan.equipment.esc.Status
RX	20:24:17.272446	00040601	E8 66 00 02 65 99 96 80	.f.e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.272446	00040601	66 59 99 64 60	fY.d`	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.272446	1E3FF27C	8A F1 A7 3F 75 64 66 DA	...?udf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.272446	1E3FF27C	D3 CC C5 40 75 71 66 DB	...@uqf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.272447	00040601	E8 66 00 02 65 99 96 81	.f.e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.272447	00040601	66 59 99 64 61	fY.da	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.280448	1E3FF27A	F9 A9 50 BD 69 64 66 C0	..P.idf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.280448	104E2001	FF D9	..	1		<unknown message 20000>
RX	20:24:17.281448	1E3FF27A	A9 12 34 3F 69 71 66 C1	..4?iqf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.281448	1F043901	CE BC 00 78 0F F6 FF 90	...x....	1		uavcan.equipment.indication.LightsCommand
RX	20:24:17.281448	07040A7A	B1 A7 00 00 00 FD 8B	122		uavcan.equipment.esc.Status
RX	20:24:17.281448	1F043901	DF F8 FF DF F7 FF DF 300	1		uavcan.equipment.indication.LightsCommand
RX	20:24:17.281448	07040A7A	4D 40 32 BB 5C 0E 0E 2B	M@2.\..+	122		uavcan.equipment.esc.Status
RX	20:24:17.281448	1F043901	FE 00 00 50	...P	1		uavcan.equipment.indication.LightsCommand
RX	20:24:17.281448	07040A7A	03 88 4B	..K	122		uavcan.equipment.esc.Status
RX	20:24:17.282449	1E3FF27A	95 ED B5 3F 75 64 66 C2	...?udf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.282449	1E3FF27A	AC B9 C6 40 75 71 66 C3	...@uqf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.282449	00040601	E8 66 00 02 65 99 96 82	.f.e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.282449	00040601	66 59 99 64 62	fY.db	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.287449	00040601	E8 66 00 02 65 99 96 83	.f.e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.287449	00040601	66 59 99 64 63	fY.dc	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.290450	1E3FF279	F2 C1 20 BC 69 64 66 C4	..idf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.290450	1E3FF279	56 35 0F 3F 69 71 66 C5	V5.?iqf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.290450	18043801	E0 66 97 2E DC	.f...	1		uavcan.equipment.indication.BeepCommand
RX	20:24:17.291450	07040A79	DF 8C 00 00 00 01 8F	121		uavcan.equipment.esc.Status
RX	20:24:17.291450	07040A79	4E 22 31 B7 5C EA 0E 2F	N"1.\../	121		uavcan.equipment.esc.Status
RX	20:24:17.291450	07040A79	02 04 4F	..O	121		uavcan.equipment.esc.Status
RX	20:24:17.291450	1E3FF279	74 EC C2 3F 75 64 66 C6	t..?udf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.291450	1E3FF279	C9 B5 C6 40 75 71 66 C7	...@uqf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.292450	00040601	E8 66 00 02 65 99 96 84	.f.e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.292450	00040601	66 59 99 64 64	fY.dd	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.297451	00040601	E8 66 00 02 65 99 96 85	.f.e...	1		uavcan.equipment.esc.RawCommand

Dir	Local Time	CAN ID	Data Hex	Data ASCII	Src	Dst	Data Type
RX	20:24:17.297451	00040601	E8 66 00 02 65 99 96 85	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.297451	00040601	66 59 99 64 65	fY.de	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.298452	10015501	96 02 00 00 00 00 00 D6	1		uavcan.protocol.NodeStatus
RX	20:24:17.298452	01000401	17 B2 71 27 00 00 00 D5	..q'....	1		uavcan.protocol.GlobalTimeSync
RX	20:24:17.302452	00040601	E8 66 00 02 65 99 96 86	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.302452	00040601	66 59 99 64 66	fY.df	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.306453	00040601	FF 95 00 00 04 00 10 87	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.306453	00040601	00 40 01 00 67	..@.g	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.312454	00040601	E8 66 00 02 65 99 96 88	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.312454	00040601	66 59 99 64 68	fY.dh	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.317456	00040601	E8 66 00 02 65 99 96 89	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.317456	00040601	66 59 99 64 69	fY.di	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.320456	10015570	45 00 00 00 00 03 00 C3	E.....	125		uavcan.protocol.NodeStatus
RX	20:24:17.320456	1E3FF27D	40 DA 76 BD 69 64 66 C8	@.v.idf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.320456	1E3FF27D	29 9C 5C 3F 69 71 66 C9)\?iqf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.320456	07040A7D	3F B1 00 00 00 00 FD 93	?.....	125		uavcan.equipment.esc.Status
RX	20:24:17.321456	07040A7D	4D 94 39 BC 5C C0 0E 33	M.9.\.3	125		uavcan.equipment.esc.Status
RX	20:24:17.321456	07040A7D	04 10 53	..S	125		uavcan.equipment.esc.Status
RX	20:24:17.321456	1E3FF27D	1B 8F AA 3F 75 64 66 CA	...?udf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.321456	1E3FF27C	8C 7E 84 BD 69 64 66 DC	..~.idf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.321456	1E3FF27D	E9 A5 C5 40 75 71 66 CB	...@uqf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.321456	1E3FF27C	BA 82 71 3F 69 71 66 DD	..q?iqf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.322456	07040A7C	73 9C 00 00 00 00 FF 80	s.....	124		uavcan.equipment.esc.Status
RX	20:24:17.322456	07040A7C	4D B9 38 B7 5C C1 0E 20	M.8.\.	124		uavcan.equipment.esc.Status
RX	20:24:17.322456	07040A7C	04 0C 40	..@	124		uavcan.equipment.esc.Status
RX	20:24:17.322456	1E3FF27C	11 E8 A6 3F 75 64 66 DE	...?udf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.322456	1E3FF27C	65 C0 C5 40 75 71 66 DF	e..@uqf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.323457	00040601	E8 66 00 02 65 99 96 8A	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.323457	00040601	66 59 99 64 6A	fY.dj	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.328458	00040601	E8 66 00 02 65 99 96 8B	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.328458	00040601	66 59 99 64 6B	fY.dk	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.330458	1E3FF27A	21 24 4A BD 69 64 66 C4	!\$J.idf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.331458	1E3FF27A	F5 AB 38 3F 69 71 66 C5	..8?iqf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.331458	07040A7A	6F 88 00 00 00 00 FE 8C	o.....	122		uavcan.equipment.esc.Status
RX	20:24:17.331458	07040A7A	4D 4E 32 BB 5C E0 0E 2C	MN2.\.,	122		uavcan.equipment.esc.Status
RX	20:24:17.331458	07040A7A	03 88 4C	..L	122		uavcan.equipment.esc.Status
RX	20:24:17.331458	1E3FF27A	EA A3 B5 3F 75 64 66 C6	...?udf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.331458	1E3FF27A	69 C3 C6 40 75 71 66 C7	i..@uqf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.332458	00040601	E8 66 00 02 65 99 96 8C	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.332458	00040601	66 59 99 64 6C	fY.dl	1		uavcan.equipment.esc.RawCommand

Dir	Local Time	CAN ID	Data Hex	Data ASCII	Src	Dst	Data Type
RX	20:24:17.340460	10015579	74 00 00 00 00 03 00 C0	t.....	121		uavcan.protocol.NodeStatus
RX	20:24:17.340460	1E3FF279	DC CB CC BC 69 64 66 C8	...idf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.340460	1E3FF279	9E F3 0E 3F 69 71 66 C9	...?iqf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.341460	07040A79	62 A3 00 00 00 00 01 90	b.....	121		uavcan.equipment.esc.Status
RX	20:24:17.341460	07040A79	4E 2B 31 B7 5C EB 0E 30	N+1.\..0	121		uavcan.equipment.esc.Status
RX	20:24:17.341460	07040A79	02 04 50	..P	121		uavcan.equipment.esc.Status
RX	20:24:17.341460	1E3FF279	E7 33 C3 3F 75 64 66 CA	.3.?udf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.341460	1E3FF279	7F B2 C6 40 75 71 66 CB	...@uqf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.342460	00040601	E8 66 00 02 65 99 96 8E	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.342460	00040601	66 59 99 64 6E	fY.dn	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.347461	00040601	E8 66 00 02 65 99 96 8F	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.347461	00040601	66 59 99 64 6F	fY.do	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.353462	00040601	E8 66 00 02 65 99 96 90	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.353462	00040601	66 59 99 64 70	fY.dp	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.356463	00040601	FF 95 00 00 04 00 10 91	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.356463	00040601	00 40 01 00 71	.@.q	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.362464	00040601	E8 66 00 02 65 99 96 92	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.362464	00040601	66 59 99 64 72	fY.dr	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.367465	00040601	E8 66 00 02 65 99 96 93	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.367465	00040601	66 59 99 64 73	fY.ds	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.370466	1E3FF27D	0E 62 80 BD 69 64 66 CC	.b..idf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.370466	1E3FF27D	96 49 56 3F 69 71 66 CD	.IV?iqf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.371466	07040A7D	06 CA 00 00 00 00 FD 94	125		uavcan.equipment.esc.Status
RX	20:24:17.371466	07040A7D	4D 09 39 BC 5C C2 0E 34	M.9.\..4	125		uavcan.equipment.esc.Status
RX	20:24:17.371466	07040A7D	04 10 54	..T	125		uavcan.equipment.esc.Status
RX	20:24:17.371466	1E3FF27D	47 A6 AB 3F 75 64 66 CE	G..?udf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.371466	1E3FF27C	20 4E 3A BD 69 64 66 C0	N:..idf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.371466	1E3FF27D	C6 B4 C5 40 75 71 66 CF	...@uqf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.371466	1E3FF27C	02 30 69 3F 69 71 66 C1	.0i?iqf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.372466	07040A7C	82 D6 00 00 00 00 FF 81	124		uavcan.equipment.esc.Status
RX	20:24:17.372466	07040A7C	4D 63 38 B7 5C C3 0E 21	Mc8.\..!	124		uavcan.equipment.esc.Status
RX	20:24:17.372466	07040A7C	04 0C 41	..A	124		uavcan.equipment.esc.Status
RX	20:24:17.372466	00040601	E8 66 00 02 65 99 96 94	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.372466	00040601	66 59 99 64 74	fY.dt	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.372466	1E3FF27C	D5 57 A7 3F 75 64 66 C2	.W.?udf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.372466	1E3FF27C	38 D3 C5 40 75 71 66 C3	8..@uqf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.378468	00040601	E8 66 00 02 65 99 96 95	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.378468	00040601	66 59 99 64 75	fY.du	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.380468	1001557A	62 00 00 00 00 03 00 DD	b.....	122		uavcan.protocol.NodeStatus
RX	20:24:17.380468	1E3FF27A	75 A5 29 BD 69 64 66 C8	u.).idf.	122		uavcan.protocol.debug.KeyValue

Dir	Local Time	CAN ID	Data Hex	Data ASCII	Src	Dst	Data Type
RX	20:24:17.381468	07040A7A	4D 60 32 BB 5C E0 0E 2D	M`2.\.-	122		uavcan.equipment.esc.Status
RX	20:24:17.381468	07040A7A	03 88 4D	.M	122		uavcan.equipment.esc.Status
RX	20:24:17.381468	1E3FF27A	9E AC B5 3F 75 64 66 CA	...?udf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.381468	1E3FF27A	74 AE C6 40 75 71 66 CB	t..@uqf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.382468	00040601	E8 66 00 02 65 99 96 96	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.382468	00040601	66 59 99 64 76	fY.dv	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.387470	00040601	E8 66 00 02 65 99 96 97	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.387470	00040601	66 59 99 64 77	fY.dw	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.390470	1E3FF279	4C 43 9A 8C 69 64 66 CC	LC..idf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.390470	1E3FF279	40 B9 0F 3F 69 71 66 CD	@..?iqf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.391470	07040A79	D6 D5 00 00 00 00 01 91	121		uavcan.equipment.esc.Status
RX	20:24:17.391470	07040A79	4E 2B 31 B7 5C EA 0E 31	N+1.\..1	121		uavcan.equipment.esc.Status
RX	20:24:17.391470	07040A79	02 04 51	..Q	121		uavcan.equipment.esc.Status
RX	20:24:17.391470	1E3FF279	E2 DB C2 3F 75 64 66 CE	...?udf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.391470	1E3FF279	98 AF C6 40 75 71 66 CF	...@uqf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.392470	00040601	E8 66 00 02 65 99 96 98	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.392470	00040601	66 59 99 64 78	fY.dx	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.397471	00040601	E8 66 00 02 65 99 96 99	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.397471	00040601	66 59 99 64 79	fY.dy	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.402472	00040601	E8 66 00 02 65 99 96 9A	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.402472	00040601	66 59 99 64 7A	fY.dz	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.406473	00040601	FF 95 00 00 04 00 10 9B	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.407473	00040601	00 40 01 00 7B	..@{	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.412474	00040601	E8 66 00 02 65 99 96 9C	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.412474	00040601	66 59 99 64 7C	fY.d	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.417475	00040601	E8 66 00 02 65 99 96 9D	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.417475	00040601	66 59 99 64 7D	fY.d}	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.420476	1E3FF27D	E9 6A 8E BD 69 64 66 D0	.j..idf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.420476	1E3FF27D	3B F3 60 3F 69 71 66 D1	;.`?iqf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.421476	07040A7D	8B 8C 00 00 00 00 FD 95	125		uavcan.equipment.esc.Status
RX	20:24:17.421476	18043801	E0 66 97 2E DD	.f..	1		uavcan.equipment.indication.BeepCommand
RX	20:24:17.421476	07040A7D	4D 84 39 BC 5C C0 0E 35	M.9.\..5	125		uavcan.equipment.esc.Status
RX	20:24:17.421476	07040A7D	04 10 55	..U	125		uavcan.equipment.esc.Status
RX	20:24:17.421476	1E3FF27C	51 2C 45 BD 69 64 66 C4	Q,E.idf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.421476	1E3FF27D	93 72 AA 3F 75 64 66 D2	.r.?udf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.421476	1E3FF27C	68 AB 68 3F 69 71 66 C5	h.h?iqf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.422476	07040A7C	2E 67 00 00 00 00 FF 82	.g.....	124		uavcan.equipment.esc.Status
RX	20:24:17.422476	1E3FF27D	1B A4 C5 40 75 71 66 D3	...@uqf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.422476	07040A7C	4D 64 38 B7 5C C2 0E 22	Md8.\.."	124		uavcan.equipment.esc.Status
RX	20:24:17.422476	07040A7C	04 0C 42	..B	124		uavcan.equipment.esc.Status

Dir	Local Time	CAN ID	Data Hex	Data ASCII	Src	Dst	Data Type
RX	20:24:17.422476	1E3FF27C	77 E5 A6 3F 75 64 66 C6	w..?udf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.423477	1E3FF27C	35 D5 C5 40 75 71 66 C7	5..@uqf.	124		uavcan.protocol.debug.KeyValue
RX	20:24:17.427477	00040601	E8 66 00 02 65 99 96 9F	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.427477	00040601	66 59 99 64 7F	fY.d.	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.430478	1F043901	00 00 00 D1	1		uavcan.equipment.indication.LightsCommand
RX	20:24:17.430478	1E3FF27A	44 EA 28 BD 69 64 66 CC	D.(.idf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.431478	1E3FF27A	87 B7 33 3F 69 71 66 CD	..3?iqf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.431478	07040A7A	D8 99 00 00 00 00 FE 8E	122		uavcan.equipment.esc.Status
RX	20:24:17.431478	07040A7A	4D 42 32 BB 5C E0 0E 2E	MB2.\...	122		uavcan.equipment.esc.Status
RX	20:24:17.431478	07040A7A	03 88 4E	..N	122		uavcan.equipment.esc.Status
RX	20:24:17.431478	1E3FF27A	37 9A B5 3F 75 64 66 CE	7..?udf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.431478	1E3FF27A	80 B8 C6 40 75 71 66 CF	...@uqf.	122		uavcan.protocol.debug.KeyValue
RX	20:24:17.432478	00040601	E8 66 00 02 65 99 96 80	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.432478	00040601	66 59 99 64 60	fY.d`	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.437479	00040601	E8 66 00 02 65 99 96 81	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.437479	00040601	66 59 99 64 61	fY.da	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.440480	1E3FF279	76 57 6C BC 69 64 66 D0	vw1.idf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.440480	1E3FF279	A2 19 0F 3F 69 71 66 D1	...?iqf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.441480	07040A79	5B 02 00 00 00 00 01 92	[.....	121		uavcan.equipment.esc.Status
RX	20:24:17.441480	07040A79	4E F2 30 B7 5C EA 0E 32	N.0.\..2	121		uavcan.equipment.esc.Status
RX	20:24:17.441480	07040A79	02 04 52	..R	121		uavcan.equipment.esc.Status
RX	20:24:17.441480	1E3FF279	44 0B C3 3F 75 64 66 D2	D..?udf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.441480	1E3FF279	18 B6 C6 40 75 71 66 D3	...@uqf.	121		uavcan.protocol.debug.KeyValue
RX	20:24:17.442481	00040601	E8 66 00 02 65 99 96 82	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.442481	00040601	66 59 99 64 62	fY.db	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.448482	00040601	E8 66 00 02 65 99 96 83	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.448482	00040601	66 59 99 64 63	fY.dc	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.452482	00040601	E8 66 00 02 65 99 96 84	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.452482	00040601	66 59 99 64 64	fY.dd	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.456483	00040601	FF 95 00 00 04 00 10 85	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.457483	00040601	00 40 01 00 65	.@.e	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.462485	00040601	E8 66 00 02 65 99 96 86	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.462485	00040601	66 59 99 64 66	fY.df	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.468486	00040601	E8 66 00 02 65 99 96 87	.f..e...	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.468486	00040601	66 59 99 64 67	fY.dg	1		uavcan.equipment.esc.RawCommand
RX	20:24:17.470486	1E3FF27D	1D AB 7F BD 69 64 66 D4	...idf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.470486	1E3FF27D	8B DC 59 3F 69 71 66 D5	..Y?iqf.	125		uavcan.protocol.debug.KeyValue
RX	20:24:17.471486	07040A7D	7A 1B 00 00 00 00 FD 96	z.....	125		uavcan.equipment.esc.Status
RX	20:24:17.471486	07040A7D	4D 6E 39 BC 5C C1 0E 36	Mn9.\..6	125		uavcan.equipment.esc.Status
RX	20:24:17.471486	07040A7D	04 10 56	..V	125		uavcan.equipment.esc.Status